



**TONE**

**DIGITORQON™ HDT-series**

Model **H3DT135**  
**H4DT200**

**TO BE PRESERVED**

**Instruction Manual No.2010**



- Read and fully understand all the instructions before use.
- Keep this instruction manual in designated place for easy and quick reference.

**TONE CO., LTD.**

Thank you for purchasing TONE DIGITORQON™ HDT-series.

- TONE DIGITORQON™ HDT-series is digital torque measurement device installed between socket and general handle like "Ratchet Handle" and "Spinner Handle"
- Over Torque Prevention Function is installed. Approaching 50%~95% of arbitrarily target torque, both an alert beep sound and Red LED go on.
- Read the instruction manual carefully before use.
- Keep the manual carefully for easy and quick reference.
- If the manual is lost or become illegible, or if additional manuals are required, contact your distributor.

**Safety Instruction**

- This manual specifies three (3) basic safety instructions.
- ⚠ DANGER** Danger is used to indicate threatening dangerous or unsafe practices which could immediately result in severe personal injury or death in the worst case.
  - ⚠ WARNING** Warning is used to indicate hazardous or unsafe practices which could result in severe personal injury or death in the worst occasion.
  - ⚠ CAUTION** Caution is used to indicate hazardous or unsafe practices which could result in personal injury or product or property damage.
- Instructions are classified by degree of risk and described as follows.

- ⚠ WARNING** Warning is used to indicate hazardous or unsafe practices which could result in severe personal injury or death in the worst occasion.
  - ⚠ CAUTION** Caution is used to indicate hazardous or unsafe practices which could result in personal injury or product or property damage.
- Even if the risk is classified as **⚠ CAUTION**, risk could become more serious result depending on conditions. Make sure to follow all instructions when using.

**Precautions for Use**

- ⚠ WARNING**
    - Do not use the device with power tools.
      - The device is only for hand use.
      - Do not apply force into the device with power tools and pneumatic tools.
    - Never use the device on live lines.
      - The device is not insulated.
      - Be sure to disconnect power source to prevent short circuit or electric shock.
- Failure to follow this instruction may result in malfunction and injury.
- Failure to follow this instruction may result in electric shock.

**Precautions for Use**

- ⚠ WARNING**
    - Handle batteries with care.
      - Install the batteries with correct polarity by referring to the markings on the battery case.
      - Do not put batteries into fire. Do not short circuit batteries.
      - Do not subject batteries to heat, deformation or decomposition.
      - Do not use new battery with old battery. Do not use dry cell with rechargeable battery.
      - If battery electrolyte enters eye, immediately rinse the eye with clean water and receive medical treatment.
      - If battery electrolyte adheres to skin or clothes, wash it off with clean water.
      - Discard of exhausted battery. Remove the batteries when the device is not in use for a long time.
      - Follow precautions on the battery.
- Failure to follow these instructions may result in fire, burn, injury, accident, malfunction, liquid leakage or out of accuracy.
- Do not use the device when its power off.
    - Failure to follow this instruction may result in malfunction due to over torque.

- ⚠ CAUTION**
  - Do not apply torque beyond maximum torque value.
    - Over torque may invite malfunction and injury.

**Precautions for Use**

- ⚠ CAUTION**
    - Apply torque slowly.
      - Never apply torque with quick motion or putting weight on the device.
      - Avoid the operations that cause a vibration or have an impact.
    - Do not abuse the device.
      - The device is a measurement tool.
    - Do not use the device in water, high-temperature and humidity condition, or nearby oil, chemical and solvent.
- Failure to follow this instruction may result in imprecise torque accuracy, malfunction of the device and/or injury.
- Failure to follow this instruction may result in imprecise torque accuracy, malfunction of the device and/or injury.
- Failure to follow this instruction may result in imprecise torque accuracy, malfunction of the device and/or injury.

**Precautions for Use**

- ⚠ CAUTION**
    - Do not use the device nearby electrical products being operated.
      - Electrical signal or noise can affect a torque measurement function of the device.
    - Insert socket to the square drive of the device completely.
      - There should be no gap between the square drive and the socket.
    - Do not use any extension bars or any joint parts.
      - Failure to follow this instruction may result in breakage of the extension bar or the joint.
    - Do not disassemble or modify the device.
      - Failure to follow this instruction may result in malfunction or accidents.
    - Keep work area clean.
      - Cluttered areas invite accidents or injury.
- Failure to follow this instruction may result in imprecise torque accuracy, malfunction of the device and/or injury.
- The gap invites injury or breakage of the square drive.
- Failure to follow this instruction may result in malfunction or accidents.
- Failure to follow this instruction may result in injury.


**Precautions for Use**

- ⚠ CAUTION**
    - After using, store the device in a designated place.
      - Clean up the device after using and then store it in a plastic case. The designated place should be dry location.
      - Also, remove the batteries when the device is not in use for a long time.
- Failure to follow this instruction may result in imprecise torque accuracy, malfunction of the device and/or injury.

**Contents of Packaging**

- Main Body
- Plastic Case
- AAA Alkaline Battery x2
- Calibration Certificate
- Instruction Manual


**Parts**



- Operation Button**
  - Press to turn on and off power.
- Tolerance Button**
  - Press to set or save the tolerance value.
- Volume up Button**
  - Press to set torque tolerance value. Press and hold to increase torque value.
- Volume down Button/Change Measurement Mode Button**
  - Press to set torque tolerance value. Press and hold to decrease torque value. Also press with Power button simultaneously to switch measurement mode.
- Set Button**
  - Press to set or save target torque.
- Clear Button**
  - Press to clear the measurement value by Peak Mode.

**Changing Batteries**

1. Unscrew the set screw for battery cover by screw driver (+No.2).
2. Slide and Remove the battery cover.
3. Install the batteries with correct polarity. When install them, the device will beep sound.
4. The device goes on automatically after installing the batteries, and then the device shuts off automatically in approx 90 seconds.
5. Slide and set the battery cover and fix it by set screw.



**Setting Torque**

- Confirm required torque value for the bolt/nut to be tightened. If torque value is not given, contact bolt manufacturers or calculate it with referring a formula below.
- $$T = K \cdot D \cdot N$$
- T: Tightening Torque (N·m)  
K: Torque Coefficient  
D: Bolt Diameter (m)  
N: Bolt Tension (kN)

**Operating Procedure**


1. Power the device on
    - Press Power Button for 3 seconds. The Red LED goes on with beep sound, and then Zero digit will appear on LCD display.
- Prior target torque value to be displayed.
- ⚠ CAUTION**
    - The device shuts off automatically when it is not in use for approx. 90 seconds with beep sound.

**Operating Procedure**

2. Set Target Torque
  - Press set button to display torque setting mode, and the value to be displayed goes on and off for approx. 6 seconds.
  - Set arbitrarily target torque value during flashing by pressing the volume button, and then press the set button again to save the target torque value with display [SAVE].

**CAUTION**

- Torque Setting mode terminates when the device is not in use during flashing (for approx 6 seconds)
- Press set button after setting the target torque. Or, the target torque is not saved.
- 3. Select Measurement Mode.
  - Following Measurement mode available.
    - Peak Mode: Display maximum torque value to be applied.
    - Track Mode: Display torque value to be applied.



**Operating Procedure**


- Peak Mode
  - The maximum torque value is displayed for 15 seconds with beep sound and then reset automatically. Or, press clear button to reset manually.
- Track Mode
  - The torque value to be displayed goes up and down depends on applied torque. "Zero" means no load.

**Setting Tolerance (Over Torque Prevention Function)**


- An alert beep sound will occur when approaching target torque. Tolerance value is to set between 5% and 50% (between 95% and 50% of the target torque).
- Press the percent button to display tolerance setting mode, and the value to be displayed goes on and off for 6 seconds. Set arbitrarily tolerance value during flashing by pressing the volume button, and then press the percent button again to save the setting tolerance value with display [SAVE].

**Operating Procedure**

- ⚠ CAUTION**
  - Setting Tolerance mode terminates when the device is not in use during flashing (for approx 6 seconds)
  - Press tolerance button after setting tolerance. Or, the setting tolerance is not saved.
  - [Over Torque Prevention Function] will not work if the torque is lower than the minimum display torque.




5. Install general handle tool and socket on the device.
  - Insert the device to the square drive of the general handle tool with no gap, and insert the socket to the square drive of the device completely.



**Operating Procedure**

6. Slide the socket over bolts and nuts to be tightened.
  - Tighten the bolts and the nuts slowly. Do not tighten them from a tilt position. Pay attention to over torque since an alert beep sound will occur when approaching target torque.



**CAUTION**

- Be careful during tightening because the device turns in the same direction as the load direction.
- The device shuts off automatically when it is not in use for approx. 90 seconds with beep sound.


**Battery Level**

- Battery level icon will appear on the LCD screen when the battery level falls by nearly 30%. Immediately change new batteries when battery level icon appears.
- 

**Repair & Maintenance**

- Accuracy might become inaccurate in case that the device is not in use for a long time or is not used properly. Contact your distributor periodically for maintenance to keep the accuracy of the device.
- Carry out overhaul once a year.
- Contact your distributor for details of handling the device.

**Specifications**



Model	10~135	9.5	45	45	24	75	0.194
H3DT135	20~200	12.7	45	45	24	75	0.184

- ※ Weight excludes batteries.
- Repeated Accuracy: +/-3% ● Battery: AAA Alkaline Battery x 2
- Torque Readout (Unit: N·m)
  - H3DT135: 0.01 increment (from 10.00 to 99.99N·m), 0.1 increment (from 100.0 to 135.0N·m)
  - H4DT200: 0.01 increment (from 20.00 to 99.99N·m), 0.1 increment (from 100.0 to 200.0N·m)
- Loading Direction: Clockwise and Counter-Clockwise Direction
- Operating Temperature: 5°C~42°C
- Storage Temperature: -20°C~50°C

**TONE**  
TONE CO., LTD.

1-57, MINATOMACHI 2-CHOME,  
NANIWA-KU, OSAKA 556-0017, JAPAN

Web Site: www.tonetool.co.jp  
e-mail: overseas@tonetool.co.jp

● Specifications and the design are subject to change without notice. ●